

PSAP Grant Program Grant Ranker

View Application--19--Mapping Server

Grant Period: 2010

Tier: Replacement of technically outdated wireless E-911 equipment or service to enable primary PSAP to maintain current service levels to the general public (**TECHNICALLY OUTDATED**)

Grant Program: Continuity and Consolidation **Grant Type:** Individual PSAP

Priority: Mapping servers and workstations (**MAPPING SUPPORT**)

Primary PSAP Applicants: Southampton County

Jurisdictions Served: Boykins, Town of
Branchville, Town of
Capron, Town of
Courtland, Town of
Ivor, Town of

Project Director:

Jerry L. Smith
Chief Communications Officer
P O Box 70 22336 Main Street Courtland VA 23837
757-653-2100 (phone)
757-653-9452 (fax)
jsmith@shso.org

Project Description:

Total Project Cost \$8,737.00

Amount Requested: \$8,737.00

Statement of Need:

Mapping server is outdated and is no longer supported by vendor. Mapping System is vital to maintaining the current level of services provided to the general public, especially those related to wireless calls and calls for service where the ability to determine location is required.

Comprehensive Project Description:

Mapping server will be replaced by installing alongside current server. Once operational the system will be replaced in a manner which will allow for minimal downtime. The replacement should be completed within two months.

How will the equipment purchased will support future technologies for PSAP readiness?:

Mapping server will have latest software version installed and is expected to be able to support future upgrades for the next 5 - 6 years.

Budget and Budget Narrative:

Mapping server replacement will include the cost of the server hardware, software and labor for hardware installation. Server - \$4,137 Software - \$4,000 Labor - \$600. Total project costs are expected to be \$8,737.

Evaluation:

Vendor will complete installation within negotiated timeline, vendor will perform tests to ensure system

functionality. Once completed PSAP will perform tests to ensure that system performs as expected and is able to completely process all expected tasks.

Attachments